












ASSEMBLY INSTRUCTION GA/GAO - 50 BED - UK


PARTS LIST

NO	DRAWING	DESCRIPTION	QTY
①		HEAD BOARD	1
②		FOOT BOARD	1
③		SIDE RAILS	2
④		MIDDLE RAIL	1
⑤		SUPPORT RAIL	3
⑥		SLAT FRAME	13


HARDWARE LIST

NO	DRAWING	DESCRIPTION	QTY
A		BOLT M8 x 15	8
B		SPANNER	1
C		BOLT M6 x 40	6
D		ALLEN KEY	1
E		SCREWS M4 x 30	14


STEP 1




STEP 2




STEP 3



STEP 4



STEP 6



STEP 5

